



**RE: Terminal 4 Slip 1 Upland Facility Pipeline and Utility Rack Footing  
Excavation Soil Sampling Letter**

**GAINER Tom** to: Madalinski, Kelly

03/22/2011 04:26 PM

Cc: Kristine Koch, mpickering, "GAINER Tom"

---

Kelly-

I reviewed the 2/1/11 *Pipeline and Utility Support Rack Footing Excavation Soil Sampling* for the T4S1 Site and have the flowing comments.

1. Please discuss the potential source of the stained soil.
2. It appears that the lateral extent of the stained soil was not determined (i.e., beyond the footing excavation).
3. While this soil contamination does not appear to be a significant threat to the Willamette River under current conditions, potential future property uses in this location should be protective of human health and the environment. This area should be included in the Site's CMMP.

Please respond to these comments within 30 days and contact me if you have questions.

Thanks-

Tom

**From:** Madalinski, Kelly [mailto:Kelly.Madalinski@portofportland.com]

**Sent:** Friday, February 04, 2011 3:11 PM

**To:** GAINER Tom

**Cc:** koch.kristine@epa.gov; WFord@LathropGage.com; Ashton, David; Barthelmess, Suzanne; Breen, David; Koehl, Krista; mpickering@ashcreekassociates.com; Lewis, Mark; Dixon, Christi; David, Sheila

**Subject:** Terminal 4 Slip 1 Upland Facility Pipeline and Utility Rack Footing Excavation Soil Sampling Letter

Attached please find the Pipeline and Utility Rack Footing Excavation Soil Sampling document for Terminal 4 Slip 1 and accompanying transmittal letter. Hard copies to follow by mail to DEQ, EPA, and Lathrop & Gage. If you have any questions, please contact me at (503) 415-6676. Thank you.

<<T4S1 Ltr DEQ Chromium SoilTransmittal (02-04-11).pdf>> <<20110201 Chromium Soil Area Report.pdf>>

**Kelly Madalinski**

Project Manager, Port of Portland

Box 3529, Portland, OR 97208

Ph: 503.415.6676 / Cell: 503.805.6952

kelly.madalinski@portofportland.com